

# SERVICE LETTER

AA-SL-24-001

## Alternator Cable Inspection

### 1. Planning Information

#### 1.1 EFFECTIVELY

HR200 and R2000 Series aircraft

#### 1.2 REASON

It has been observed that there is potential for the wires connected to the rear of the alternator to be fitted incorrectly following maintenance resulting in possible chafing and shorting of wires.

#### 1.3 RECOMMENDED ACTION

It is recommended that during the next maintenance visit inspect the cables common to the rear of the alternator.

#### 1.7 WEIGHT AND BALANCE

N/A

#### 1.8 REFERENCES

Alpha Aviation HR200 and R2000 Service Manual, as applicable.

#### 1.9 OTHER PUBLICATIONS AFFECTED

N/A

### 2. Material Information

#### 2.1 MATERIALS IDENTIFICATION

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>
-	-	-

#### 2.2 CONSUMABLES

N/A

#### 2.3 OTHER PUBLICATIONS AFFECTED

N/A

#### 2.4 SPECIAL TOOLING

NA

# SERVICE LETTER

AA-SL-24-001

## Alternator Cable Inspection

### 3. Accomplishment Instructions

Inspect the cables common to the rear of the alternator.

Ensure that all cables appropriately routed, supported and there are no signs of taut, distressed or chafed cables.

### Contact Information:



Ingram Road  
Hamilton Airport  
RD 2  
Hamilton 3282  
NEW ZEALAND

Phone: + 64 7 843 7070    Fax: + 64 7 843 8040  
Web: [www.alphaaviation.co.nz](http://www.alphaaviation.co.nz)

**\*\*\*\*\*This Publication is for information, guidance, or advisory purpose only and may not be used as "CAA Approved" data with respect to aircraft operation or continued airworthiness'\*\*\*\*\***