

AVIONS PIERRE ROBIN

DIJON

France

SERVICE

SERVICE BULLETIN N° 61

Subject : Service life of top engine bearer attachments.

Aircraft concerned : All types of HR 200 aircraft, up to Serial n° 89 inc.

Date : 26/8/1975

Page : 1/1

Date of application : see below

Approved by : S.G.A.C.

The top engine bearer attachments which up till now have been fitted on HR 200 aircraft (Serial n°1 to 89 inclusive), have a service life limited to 5000 hours.

These fittings may be changed during the Major Inspection preceding the 5000 flying hours threshold.

This operation can be carried out only by one of the ROBIN Service Stations, or by specialists detached from our Company. Our network will therefore be at your disposal whenever you require it.

The new attachments to be fitted (n° 22.23.17, index 2) have not yet been assigned a service life.

I  
M  
P  
E  
R  
A  
T  
I  
V  
E