

AVIONS ROBIN

1, route de Troyes 21121 DAROIS - FRANCE Tél. 33 (0)3 80 44 20 50 Fax: 33 (0)3 80 35 60 80

LETTRE SERVICE N°43 / SERVICE LETTER N°43

OBJET
Déflecteur moteur

AVIONS CONCERNES
HR200/100, HR200/100S
R2100, R2100A
DR400 2+2
DR315, DR300/108

Les déflecteurs équipant les moteurs O-235 C2A, O-235 C2C ou O-235 H2C, en particulier les éléments inter-cylindres, ne sont pas fournis par le constructeur du moteur Textron-Lycoming.

En conséquence, pour éviter qu'ils ne soient égarés ou remplacés abusivement lors des opérations de révision chez le motoriste, nous conseillons de les déposer de chaque moteur et de les conserver en vue de leur remontage.

SUBJECT
Engine baffles

AIRCRAFT AFFECTED
HR200/100, HR200/100S
R2100, R2100A
DR400 2+2
DR315, DR300/108

The baffles fitted on O-235 C2A, O-235 C2C, or O-235 H2C engine, particularly the elements between cylinders, are not supplied by Textron-Lycoming engine manufacturer.

Consequently, to avoid the lost or the wrong replacement of the baffles during maintenance operations at the engine manufacturer, we recommend to remove them from the engine and to keep them until future reassembly.