



APEX Aircraft Bureau de Navigabilité 1, route de Troyes 21121 DAROIS - France Tél +33 380 35 65 10 Fax +33 380 35 65 15 www.apex-aircraft.com	<h1>S E R V I C E L E T T E R</h1> <p>No. 031206</p>
LANDING GEAR - Air filling valve mechanism (core)	
Supersedes : N/A	

ATA : 32

This document is a courtesy translation of its original French version.
In case of any difficulty, reference should be made to the French original issue.

EFFECTIVITY

Models	Serial numbers affected
CAP10B	From s/n 300 and airplanes having performed modification 000302 "CAP10C wing"
DR400 tous modèles	All
R2000 tous modèles	All
HR200 tous modèles	All
R3000 tous modèles	All
HR100 tous modèles	All
R1180 tous modèles	All

REASON - DESCRIPTION

The landing gear air filling valve mechanism installed until now are no longer available. APEX Aircraft makes approved new mechanism s available to users.

The aim of this Service Letter is to provide the users with the order reference of the new air filling valve.

MATERIAL

Material (supplies) consist of old and/or new parts as listed in section 'MATERIAL INFORMATION' of this SB. Spare parts can be procured from APEX Aircraft (Tel: +33 380 35 61 98, Fax: +33 380 35 60 58, E-mail: parts@apex-aircraft.com).

TOOLING - ACCOMPLISHMENT INSTRUCTIONS

Standard tools.

The installation of the new air filling valve is to be done the same way as the previous ones.

REFERENCES

« Dossier d'Evolution Technique » DET 031206 MINOR modification approved by EASA.

PUBLICATIONS AFFECTED

- Aircraft Parts catalog: insert a copy of this Service bulletin until the next update.
- Service Letter 7 SB/SL list for Avions Robin: to update.
- Service Letter 990813 SB/SL list for CAP: to update.



FEEDBACK

Please inform APEX Aircraft Airworthiness Office about the implementation of the inspection/change described in this Service Bulletin.

You may use:

- postal mail: address on the first page of this Service Bulletin,
- fax : (+33) (0) 380 356 515,
- e-mail: airworthiness@apex-aircraft.com,
- the APEX Aircraft web page: <http://www.apex-aircraft.com>.

MATERIAL INFORMATION

Airplane	New part number	Key word	Old part number	Instructions
CAP10C	41-12-03-021	Air filling valve mechanism or core <i>Mécanisme ou obus de valve</i>	41-56-32-001	To replace depending on parts wear
DR400, R2000, HR200, HR100, R3000, R1180	41-12-03-021	Air filling valve mechanism or core <i>Mécanisme ou obus de valve</i>	41-12-03-020	To replace depending on parts wear
<i>For current prices, contact APEX Aircraft.</i>				