

AVIONS PIERRE ROBIN

Aérodrome de DIJON - VAL SUZON

21121 Fontaine .lès .Dijon

Tel. (80) 31 61 01 — Telex 350 818

FRANCE

BULLETIN DE SERVICE
SERVICE BULLETIN

N° 24

R E C O M M E N D E D

Objet Object : Equipment concerned : Air intake filter

Motive : Verification and replacement of filters

Aircraft concerned : All aircraft equipped with an air intake

Date :

Approuvé par la DGAC Approved by DGAC

6-01-1971

REMARKS :

Our After-Sale Service has found that the air intake filters of numerous aircraft in service were in a very bad state. This filter plays a very important role in the potential life of the engine and must be the object of particular attention. It is therefore recommended to :

- 1) Check the filtering element at each preflight inspection, in accordance with your Flight Manual, for cleanliness (absence of grass, mud, etc...) and condition (presence of filtering material).
- 2) Remove and clean the filtering element every 25 flying hours.
- 3) Change the filtering element every 50 or 100 hours, according to operating conditions (training flights, sandy airfield, grass or earth runway, etc...).

You can obtain spare filters from our Service Stations, as well as a maintenance guide which will help you make the best possible use of your aircraft.