

AVIONS PIERRE ROBIN

Aérodrome de DIJON-VAL SUZON

— 21121 Fontaine .lès .Dijon

Tel. (80) 31 61 01 — Telex 350 818

FRANCE

BULLETIN DE SERVICE
SERVICE BULLETIN

N° 78

RECOMMANDE - RECOMMENDED

Objet Object : RESERVOIR ESSENCE 52.23.01.000
FUEL TANKS 52.23.01.000

Avions concernés : R 2100 - R 2100 A - R 2160 - R 2160 D - R 2112 -
HR 200 TOUS TYPES

Aircraft : R 2100 - R 2100 A - R 2160 - R 2160 D - R 2112 -
concerned HR 200 ALL TYPES

Date :

Novembre 1979

Edition 1

Page 1/1

Approuvé par la DGAC Approved by DGAC

15 janvier 1980

Quelques cas de fuites ayant été observés sur les réservoirs de carburant des avions cités ci-dessus, nous vous informons de l'existence d'un kit de réparation de ces réservoirs (kit de réparation n° 97.23.21).

Seuls les ateliers agréés ROBIN seront habilités à effectuer cette réparation et destinataires du plan de réparation.

NOTA : Plan joint pour les ateliers agréés.

=====

Since a few cases of leakage have been noted on the fuel tanks of the above mentioned aircraft, we would like to inform you that a repair kit is available for such tanks (Repair Kit n° 97.23.21).

ROBIN approved workshops alone are authorized to carry out such repair work and entitled to receive the repair drawing.

NOTE : Attached drawing for approved workshops.