

AVIONS PIERRE ROBIN

Aérodrome de DIJON-VAL SUZON

21121 Fontaine .lès .Dijon

Tel. (80) 31 61 01 — Telex 350 818

FRANCE

LETTRE DE SERVICE
SERVICE LETTER**N°** 17**Objet** Object : RECTIFICATION DES BULLETINS DE SERVICE N° 84 - 85 - 86.
*RECTIFICATION SERVICE BULLETIN N° 84 - 85 - 86*Avions concernés : Voir bulletin de serviceAircrafts concerned : See Service Bulletin

| | | |
|---|------------------------|-----------------|
| <u>Date</u> septembre 1980 <i>september 1980</i> | <u>Edition Issue</u> 1 | <u>Page</u> 1/1 |
|---|------------------------|-----------------|

Une erreur s'est glissée dans les Bulletins de service n° 84 - 85 - 86 du mois de juillet 1980, relative à la mention : AVIONS CONCERNES

Il faut lire :

Bulletin de service n° 84 : Avions concernés : R 2000 tous types

Bulletin de service n° 85 : Avions concernés : R 2000 tous types

Bulletin de service n° 86 : Avions concernés : DR 400 jusqu'au n° 1489

R 1000 jusqu'au n° 268

R 2000 jusqu'au n° 191

HR 100 tous numéros

Merci d'apporter cette modification sur vos bulletins de service.

There is a mistake in Service Bulletins nr 84 - 85 - 86 date july 1980, about mention of : AIRCRAFTS CONCERNED

Must read :

Service Bulletin nr 84 : Aircrafts concerned : R 2000 all types

Service Bulletin nr 85 : Aircrafts concerned : R 2000 all types

Service Bulletin nr 86 : Aircrafts concerned : DR 400 up to serial 1489

R 1000 up to serial 268

R 2000 up to serial 191

HR 100 all nr

Thank you for your attention.