

# AVIONS PIERRE ROBIN

1, Route de Troyes 21121 DAROIS-FRANCE TEL: 80 35 61 01 FAX: 80 35 60 80 TLX: 350 818 ROBIN

## LETTRE DE SERVICE N°28 rév. 2 / SERVICE LETTER N°28 rev. 2

### OBJET

VOL SANS CARRENES DE ROUES

### AVIONS CONCERNES

Tous type ROBIN à train fixe

\* \* \*

A titre exceptionnel, pour éviter l'immobilisation des avions à train fixe, nous autorisons les vols sans carènes de roues.

Toutefois, nous attirons votre attention sur le fait que les performances sont modifiées de façon suivante:

- Performances de décollage:  
La distance de passage des 15 m est à augmenter de 3%,
- Performances de montée:  
La VZ est à diminuer de 3%,
- Performances de croisière:  
Les vitesses en palier sont à diminuer de 6%.

### SUBJECT

OPERATION WIHTOUT WHEEL SPAT

### AIRCRAFT AFFECTED

*All ROBIN types with fixed landing*

\* \* \*

*Exceptionally, and to avoid the grounding of aircraft with fixed landing gear, flight without wheel spats are authorized.*

*However, it must be noted that performance data are modified as follows:*

- *Take-off performance:*  
*Run to clear 15 m barrier increased by 3%,*
- *Rate of climb:*  
*Vz decreased by 3%,*
- *Cruise performance:*  
*Level flight speeds decreased by 6%.*