

**AVIONS PIERRE ROBIN**

Aérodrome de DIJON-VAL SUZON

21121 Fontaine-lès-Dijon

Tel. (80) 31 61 01 — Telex 350 818

FRANCE

**LETTRE DE SERVICE  
SERVICE LETTER****N°20****Objet** Object : Air filter fitting check**Aircraft concerned** : DR 400

HR 200

R 2000

Equiped with the below mentioned air filter.

**Application** : AS SOON AS YOU RECEIVE SERVICE LETTER.

<u>Date</u>	<u>Edition</u> <u>Issue</u>	<u>Page</u>
2 février 1981	1	1/2

- CHECK the air filter fitting

Type : - MICROTOP (Mann C 1842)

- MIOFILTRE (GX 03183 01A)

- LAUTRETTE (FLAA 3036)

- The air filter is fitted by 4 CHC screws  $\emptyset$  5 x 22.

According to the annexed drawing, there should be among others with each screw :

- 3 washers  $\emptyset$  5 x 16 (Ref. 1)

- 1 strut of 110 mm lenght (Réf. 2).

- CHECK (On each CHC screw)

1) That the 3 washers are installed according to the draving.

2) That the strut length is actualy 110 mm

- If these two conditions are not fulfilled, replace or insert the corresponding items.

**Important** : we remind that cleaning and checking the condition of the air filter is due according to the maintenance manual every 50 hours on all aircraft (see S.B. n° 24).

